



OFFICE PARK - ANAHEIM, CA

PROJECT DESCRIPTION

A 1.5" FORTA-FI[®] reinforced overlay was used to rehabilitate the badly deteriorated parking lots and drive aisles around this commercial office development. Existing pavement distresses included severe alligator cracking and some areas where rutting was prevalent.

UPDATE

Nine months after construction, the FORTAfi[®] overlay is holding up well and **shows no signs of cracking**. The pavement was edge-milled to 4' prior to placing the overlay.

KEY POINTS

- Extended Pavement Life
- Reduced Rutting & Raveling
- Reduced Cracking

DETAILS

Date: 2015

Location: Anaheim, CA

Fiber: FORTA-FI[®]

Tonnage: 650

Distributor: Pacific GeoSource



**PACIFIC
GEOSOURCE**